



Summary



Industry:	Food - Dairy
Application:	Pump
Actual Saving:	£Undisclosed
Payback Period:	Undisclosed



ERIKS Provide a Replacement for a Leaking Pump

ERIKS Specialists Track Down the Origin of an Unidentifiable Problematic Pump

ISSUE

A dairy manufacturer had an unidentifiable leakage by a pump in a chiller plant room at one of their sites. However, the pump had no plate or motor details to enable easy identification of the model.

SOLUTION

ERIKS experts identified the manufacturer of the pump. Then, the search for a suitable replacement was narrowed down by taking the pump's measures and referring to archived manufacturer information to enable the ERIKS team to obtain the old pump data and provide the available options for a modern day replacement.

Based on the findings, a replacement pump was chosen and ordered by the customer along with the necessary spacer kit which allowed for the pump to be installed without any pipe alterations.

OTHER BENEFITS

- ERIKS Technical Know-How
- Improved Efficiency
- Reduced Downtime

FURTHER COMMENTS...

The new pump is now up running. The customer is pleased with ERIKS' technical know-how and is willing to use ERIKS' services in the future.

MORE INFORMATION

ERIKS Industrial Services

Amber Way, Halesowen,
West Midlands B62 8WG

Tel: 0845 006 6000

Web: www.eriks.co.uk

know-how makes the difference

ERIKS