

PROBLEM SOLVER

CUT CORROSION FROM FREQUENT WASHDOWNS

FESTO

Problem: A large food manufacturer was experiencing frequent issues on part of their mixing line.

Over time, the frequent wash down procedures were corroding the cylinders on the aluminium barrels.

Solution: Following a quick inspection of the application the customer was advised to switch to Festo's DSBF cylinders.

The DSBF cylinders incorporate Festo's 'all clean design' which eliminates unnecessary cavities reducing potential bug traps - whilst providing excellent corrosion protection. In addition the cylinders are resistant to conventional cleaning agents, and perfect for use in splash zones and where frequent wash downs are required.

Food and
Beverage

