PROBLEM SOLVER

THE GREENER CLEANER OPTION

Fenner®

Reliable | Trusted | Connected

Problem: A large pet food manufacturer contacted ERIKS as it was experiencing issues with the roller chains on its conveyor system.

> The chains were failing after just six months and were contaminated with debris attracted by the excess oil applied to the conveyor.

Solution: Following technical discussions, the **Fenner® PLUS lubrication-free chain** was suggested. Utilising sintered bush chain technology, which negates the need for pre-lubrication, it also reduces the risk to personnel as they don't have to climb into machinery.

100m were trialled and over a year later, are still in full working order, with further chains being fitted.



